



PRODUCT DATA SHEET

INDUSTRIAL RANGE

UNIVERSAL UNDERCOAT

1. DESCRIPTION

Good quality general purpose undercoat based on a modified alkyd resin.

2. PRINCIPAL CHARACTERISTICS

- Intermediate undercoat in the ECONOMY RANGE.
- Excellent opacity and adhesion on correctly prepared and primed internal and external substrates.
- Good application with excellent brushing and leveling properties. Must be over coated with compatible conventional alkyd or water-based paints.
- Provides a smooth base for top coats.

3. PACKAGING, COLOURS AND GLOSS

- 1lt, 5lt and 20lt.
- White.
- Matt finish.

4. BASIC DATA AT 23°

- Drying time: \pm 4hrs surface dry.
 \pm 16hrs full cure.
- Recoating time: \pm min 16hrs for 45 μ m dft, max unlimited.
- Pot life: N/a
- Induction period: N/a
- Mass relative density: \pm 1.35 – 1.45 g/cm³.
- Solids by volume: \pm 45%.
- Viscosity: \pm 70 – 75 Ku.
- Recommended dft: 45 μ m per coat. (2 coats recommended.)
- Theoretical spreading rate: 8 – 10m²/lt for 45 μ m.
- Practical spreading rate: 6 – 8m²/lt for 45 μ m.
- Shelf life: at least 12 months in cool and dry conditions.



PROTECTION WHERE YOU NEED IT!

Limitation of liability applies. Refer to annexure for full disclosure.
April 2009 - INDUSTRIAL RANGE - HB EPOXY PIPE COAT - revision 1 of 2009.



- Flash point: 36°C to 43°C.

5. RECOMMENDED SUBSTRATE CONDITIONS AND TEMPERATURES

- Previous coat: (alkyd or water-based primer) must be free from any contamination and sufficiently abraded if necessary.
- The substrate must be dry, surface moisture content less than 15%, before and during application of ECONOMY UNIVERSAL UNDERCOAT.
- Substrate temperature should be between 10°C and 30°C and at least 3°C above dew point during application and curing.
- Maximum relative humidity during application and curing is 85%.

6. INSTRUCTIONS FOR USE

- Stir well before use.
- Product temperature of the stirred base should be above 15°C to achieve application viscosity.
- Product is formulated to be ready for use; the addition of mineral turpentine will reduce sag resistance and opacity.
- Always ensure adequate ventilation.

• AIRLESS SPRAY:

- Recommended thinner: Mineral turpentine.
- Volume of thinner: Thinning not recommended.
- Nozzle orifice: ± 0.38 – 0.48mm.
- Nozzle pressure: 12 – 16MPa (± 120 to 160 bar).

• AIR SPRAY:

- Recommended thinner: Mineral turpentine.
- Volume of thinner: 0 – 5%, depending on required thickness and application conditions.
- Nozzle orifice: ± 1.5 – 2mm.
- Nozzle pressure: 0.3 – 0.4MPa (± 3 to 4 bar).

• BRUSH / ROLLER:

- Recommended thinner: Long haired brush or mohair roller.
- Recommended thinner: Mineral turpentine.
- Volume thinner: Thinning not recommended.
- Cleaning solvent: Mineral turpentine.

7. SAFETY PRECAUTIONS

This is a solvent based undercoat, avoid inhalation of spray mist vapor as well as contact between the wet paint and exposed skin or eyes.



PROTECTION WHERE YOU NEED IT!

Limitation of liability applies. Refer to annexure for full disclosure.
April 2009 - INDUSTRIAL RANGE - HB EPOXY PIPE COAT - revision 1 of 2009.